

Appendix C

Audited CP Solutions Photos

Ma An Shan – Shan Ying Mill

CP Solution #4



Photo 1: Hydraulic oil recovery

This picture shows the hydraulic oil recovery drums (in the background) and the mill's sewer (in the front) where hydraulic oil was disposed of before the implementation of this solution.

CP Solution #5



Photo 2: Starch and polymer dosing equipment

Ma An Shan-Shan Ying mill is now adding some starch and polymer to the wet end of their paper machines. This solution allows the mill to reduce its fiber consumption and to increase the quality of its products. Photo 2 shows the starch and polymer dosing equipment.